


RELEASE NOTES

Components	Versions
API software	2.1
UTView_64.exe	
UTView_32.exe	
Library	7,0
Sidev_64.dll	
Sidev_32.dll	
Additional programs	2.0
SIPATOOLS_64.exe	
SIPATOOLS_32.exe	
Firmware	
FAAST-PA	frm_pa_080719.bin
SOCO-X-UT	frm_soco_141019.bin
Configuration files	
For all devices	cfg_generic_141019.bin
Additional files	1 00 0007101:
FAAST-PA	cfg_pa_1x32_080719.bin, cfg_pa_2x32_080719.bin, cfg_pa_3x32_080719.bin, cfg_pa_4x32_080719.bin,
	cfg_pa_1x64_080719.bin, cfg_pa_2x64_080719.bin,
	cfg_pa_1x96_080719.bin, cfg_pa_1x128_080719.bin,
	cfg_pa_1x32_128_080719.bin
	0.9 <u>~ </u> 0
SOCO-XP-UT	cfg_soco_xp_141019.bin
SOCO-8S-UT	cfg_soco_8s_141019.bin
5000 1 HT	of a constant 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
SOCO-1-UT SOCO-1AB-UT	cfg_soco_1_141019.bin
Interface modules	
INTLOG IN:	INITI OC INI V O 2 not
INTANA OUT:	INTLOG_IN_V_2_3.pof
INTLOG OUT:	INTANA_OUT_V_2_3_1.pof
INILOG_OUI.	INTLOG_OUT_V_2_3_1.pof

New/Improved features



Bug fixed

ID	Description
	A correction has been done to improve the boot of FAAST-PA
	The firmware has been updated to properly manage the FAAST-PA 1x96
	A correction has been done to control the high voltage of SOCO-8S-UT and SOCO-XP-UT devices.
	A correction has been done on TOF and WT analog outputs when Gate IF is disabled and when the range is less than 640ns.



Tel: (33) 1 64 63 81 09 Fax: (33) 1 64 63 60 21