


# **RELEASE NOTES**

Software & firmware versions	2 -
New/Improved features	3 -
Bugs fixed	6 -
Bug fixed and improvements by patch 1	6 -
How to upgrade an existing system	7 -

#### Software & firmware versions

Components	Vorsions	
Components APL software	Versions	
API software UTView_64.exe	3.1	
=		
UTView_32.exe		
Configuration file	E	
UTView.ini	5.5	
Language files	2.5	
English.xml		
French.xml	0.4.1	
Library	8.4.1	
sidev_64.dll		
sidev_32.dll	0.5	
Additional programs	2.5	
SIPATOOLS_64.exe		
SIPATOOLS_32.exe		
Firmware	0.10	Firmware for FAAST-PA :
Service	9.10	frm_pa_250621.bin
		Firmware for SOCO-SCAN & SOCO-SWIFT-PA : frm_ssw_250621.bin
		Firmware for SOCO-X-UT :
		frm_soco_250621.bin
		Configuration files for all devices :
		cfg_generic_290621.bin
		Additional files for FAAST-PA :
		cfg_pa_1x32_080719.bin, cfg_pa_2x32_080719.bin,
		cfg_pa_3x32_080719.bin, cfg_pa_4x32_080719.bin,
		cfg_pa_1x64_080719.bin, cfg_pa_2x64_080719.bin,
		cfg_pa_1x96_080719.bin, cfg_pa_1x128_080719.bin,
		cfg_pa_1x32_128_080719.bin
		Additional files for SOCO-SCAN :
		cfg_soco_scan_1x16_250621.bin, cfg_soco_scan_1x32_250621.bin,
		cfg_soco_scan_plus_1x16_250621.bin,
		cfg_soco_scan_plus_1x32_250621.bin
		Additional files for SOCO-SWIFT :
		cfg_soco_swift_1x64_250621.bin,
		cfg_soco_swift_1x96_250621.bin,
		cfg_soco_swift_1x128_250621.bin,
		cfg_soco_swift_1x256_250621.bin,
		cfg_soco_swift_plus_1x32_250621.bin,
		ctg_soco_swift_plus_1x64_250621.bin, cfg_soco_swift_plus_1x128_250621.bin,
		cfg_soco_swift_plus_1x256_250621.bin,
		Additional files for SOCO-XP-UT :
		cfg_soco_xp_141019.bin
		Additional files for SOCO-8S-UT :
		cfg_soco_8s_141019.bin
		Additional files for SOCO-1-UT & SOCO-1AB-UT:
		cfg_soco_1_141019.bin
WebAdmin	1.3.1	
SocomatePlatformManager	1.1.3	
Interface modules		201/10/201/201
INTLOG_IN:	3.0	INTLOG_IN_V_3_0_0.pof
INTANA_OUT:	2.3.1	INTANA_OUT_V_2_3_1.pof (model < c)
	<mark>3.1.4</mark>	INTANA_OUT_V_3_1_4.pof (model≥c)
INTLOG_OUT:	2.3.1	INTLOG_OUT_V_2_3_1.pof (model < b)
	<mark>3.1.3</mark>	INTLOG_OUT_V_3_1_3.pof (model≥b) Where is indicated model

#### New/Improved features



A new COMPRESSED_AS_USPC A-scan mode has been added. This mode is reserved for SOCO-X products at FS=200MHz. This mode has been designed to return the A-scan signal as the old USPC products done.
A new S-scan mode has been added. The tab sequence has been modified to manage this mode. New tabs have been added to calibrate the S-scan and to set a DAC You can call Bscan_xx program to get a graphic representation of S-scan during the calibration process. Synchronization Receiver Scope Gates Probe Geometry Emission Detection DDF Sequence Scanning calibration Mechanical alignment Search law Sscan cali Sequence 1 /128 Name 30.0* Pulser Sequence Multiple assignment Uppendency Start 30.0* (1) Sequence Multiple assignment Uppendency Start 1:00* (1) 30.0* (1) Sequence Scheduler Multiple assignment Uppendency Repetition 1 Interfacing Scan inc.(elements) 1 Oppendency Run each sequence N times Oppendence N times Oppenden
NOTE: This mode works with new laws calculated with SIPATOOLS 2.5
Now, the time performances are displayed to know the maximum achievable performance according to the current settings.
New alarm process to check temperatures and voltage has been embedded. This process periodically checks these parameters to set LED status.
Improvement of plugins Displaying a message box to apply changes if certain changes were detected when the operator exits the current tab.
 <ul> <li>Improvement of IO cards performances</li> <li>Improve boot process (auto-check)</li> <li>Increase the cable length up to 50m</li> <li>Manage a LED to indicate the status of the cards</li> <li>Enable IO card with SOCO-SCAN and SOCO-SWIFT</li> <li>Correct a bug of the output of TOF (was 5V when TOF = 0usec)</li> <li>Reset the output to 0V when an IO pin is unselected.</li> </ul>
<ul> <li>New parameters are available with the DLL:</li> <li>"sync_period_min", "sequence_time_min" to get time performance</li> <li>"path" to get X, Y coordinate of points of the A-scan signal (*).</li> <li>"gate_path" to get X, Y coordinate of points of the gates (*).</li> <li>"gateX_projection", "gateX_relative_projection" to get the X, Y coordinate of a distance measured into a gate (*).</li> <li>"gatex_inversed_projection", "gatex_relative_inversed_projection" to get an ultrasonic distance from an X, Y coordinate (*).</li> <li>(*) Request a "law" created by the new SIPATOOL program. These parameters are used for</li> </ul>
 B and S-scan representation. Improvement of Scanning-tool to calibrate the multi-beams configuration in one shot.

	The new DLL checks the INI configuration file to detect incompatibilities between selected options.
	Example: COMPRESSED_AS_USPC is not available for FAAST-PA, SOCO-SCAN and SOCO-SWIFT.
	An error will be detected and you could find details into the log file.
	The frequency sampling at 66.6MHz has been removed.
Behaviour	
has been	
changed	


### Bugs fixed

ID	Description
	The firmware has been updated:
	<ul> <li>To return all data on finite number of triggers.</li> </ul>
	<ul> <li>To improve a dead zone at the beginning of the A-scan.</li> </ul>
	<ul> <li>To run A-scans with COMPRESSED and EXTENDED mode at 8/9 bits for all</li> </ul>
	frequency sampling.
	<ul> <li>To improve the element calibration process by eliminating inactive elements</li> </ul>
	<ul> <li>To improve the Y calibration of the A-scan signal.</li> </ul>
	<ul> <li>To improve the loading of the firmware when we change the A-scan mode.</li> </ul>
	<ul> <li>To force divider to 1 when internal trigger is selected.</li> </ul>
	<ul> <li>To correct the management of LED READY. It was OFF when a UT file designed for element calibration was loaded.</li> </ul>
	To correct interlacing mode.
	<ul> <li>Sends interlacing value to file upload</li> </ul>
	<ul> <li>Auto recalculate the interlacing value if the repetition number changes</li> </ul>

## Bug fixed and improvements by patch 1

ID	Description
#388	Correct a bug when gates use inches
#370	Add missing source codes for LabView developers.
#334	Add signal description of K2 connector of SOCO-X cards.
#335	Correct the Developer's manual. "device%d_hv" command description wasn't correct.
#312	The 32 bit Detection plugin (for Phased Array devices) wasn't up to date.
#387	The firmware of the Interface output cards have been improved.
#400	
#405	
#379	Update VFAnalyzer program (a tool to check version files)

#### How to upgrade an existing system



SOCOMATE INTERNATIONAL 8 Rue des Abbesses 77580 Crécy la chapelle FRANCE Tel: (33) 1 64 63 81 09 Fax: (33) 1 64 63 60 21