



RELEASE NOTES – Patch 1

Components	Versions
API software USPC7100.exe	4.5.1
Library USPC7100.dll	11.0.7
Firmware configuration (for USPC cards):	config7108c.cod config7158d.cod config712o.cod
Firmware configuration (for FFAST cards):	FA021215.000 FG010216.000 FC021115.000 FF220415.000 FE110711.000 FT280514.000 FP191113.000
Driver for Windows 7/10 SIAMCCWDF.sys	4.5
USPC Windows service USPC7100WinService.exe	4.0.0.16
ActiveX USPC (only for 32 bits) XUSPC7100.ocx	2.1.0.0
Plugins SIPATOOLS	2.0.1

New features

ID	Description

Bug fixed

ID	Description
235	The DAC curve was corrupted when the duration of the DAC was changed after its creation. The new DLL solves this problem.
236	The DAC was not properly duplicated with duplication features. The new DLL solves this problem.

How to apply the patch?

From a new system:

1. Install USPC7100 4.5.1 with the setup32 or setup64 program.
2. Copy the DLL from "ImageUSB/Patch1/32" or "ImageUSB/Patch1/64" according to your system to "c:\windows\system32".

From an existing system:

1. Download the patch 1 from www.socomate.com
2. Copy the DLL from "Patch1/32" or "Patch1/64" according to your system to "c:\windows\system32".

SOCOMATE INTERNATIONAL
8 Rue des Abbesses
77580 Crécy la chapelle
FRANCE
Tel: (33) 1 64 63 81 09
Fax: (33) 1 64 63 60 21