



RELEASE NOTES – Patch 2

| Components | Versions |
|--|--|
| API software USPC7100.exe | 4.5.1 |
| Library USPC7100.dll | 11.0.9 |
| Firmware configuration (for USPC cards): | config7108c.cod config7158d.cod config712o.cod |
| Firmware configuration (for FAAST cards): | FA021215.000 FG010216.000 FC021115.000 FF220415.000 FE110711.000 FT280514.000 FP191113.000 |
| Driver for Windows 7/10 SIAMCCWDF.sys | 4.5 |
| USPC Windows service USPC7100WinService.exe | 4.0.0.16 |
| ActiveX USPC (only for 32 bits) XUSPC7100.ocx | 2.1.0.0 |
| Plugins SIPATOOLS | 2.0.1 |

New features

| ID | Description |
|----|-------------|
| | |
| | |

Bug fixed

| ID | Description |
|-----|---|
| 425 | An incorrect gain value was set when the gain was changed during the acquisition process. |
| 246 | An exception occurs if the path to the application calling the DLL is too long (>260 characters). This is often the case for applications written in Java. |

How to apply the patch?

From a new system:

1. Install USPC7100 4.5.1 with the setup32 or setup64 program.
2. Copy the DLL from "ImageUSB/Patch2/32" or "ImageUSB/Patch2/64" according to your system to "c:\windows\system32".

From an existing system (if USPC 4.5.1 is already installed):

1. Download the patch 2 from www.socomate.com
2. Copy the DLL from "Patch2/32" or "Patch2/64" according to your system to "c:\windows\system32".

SOCOMATE INTERNATIONAL
8 Rue des Abbesses
77580 Crécy la chapelle
FRANCE
Tel: (33) 1 64 63 81 09
Fax: (33) 1 64 63 60 21