



## USPC Release Notes

V6.4.5.5

You received a new version of USPC package.

This package holds a new DLL and a new API software.

API software V6.4.5.5

DLL V11.0

Configuration files:

config65.cod,

config298.cod,

config91.cod (for V2.1 hardware),

config502.cod (for V3.2 hardware).

Driver V3.3.2 for Windows 2000/XP

PCXUS.TXT V9.0

PCXUS.INI V7.0

ActiveX USPC 1.9.0

## **New features**

Nothing

## **Fixed issues**

Configuration file “config64.cod” introduced a mistake.  
Channels were mixed when acquisition was running.  
This version solves this problem.



SOCOMATE INTERNATIONAL  
8 Rue des Abbesses  
77580 Crécy la chapelle  
FRANCE  
Tel: (33) 1 64 63 81 09  
Fax: (33) 1 64 63 60 21